

## NOTICE!!!

### 1970 CHRYSLER E-BODY

#### HORN RELAY INTERCHANGE

Your original 1970 E-body Dash Harness used a slightly different Fuse Block than the 1971-up vehicles. The only difference was the configuration of the Horn Relay. Due to the fact that we had to consolidate our tooling in the reproduction of these harnesses, we have used the 1971-up Fuse Block on your harness. This horn relay Chrysler part number 3579204 (1971-73 B and E Body) can be purchased separately under part NG1018.

NOTICE SHEET

92963521

## NOTICE!!!

### 1970 CHRYSLER E-BODY

#### HORN RELAY INTERCHANGE

Your original 1970 E-body Dash Harness used a slightly different Fuse Block than the 1971-up vehicles. The only difference was the configuration of the Horn Relay. Due to the fact that we had to consolidate our tooling in the reproduction of these harnesses, we have used the 1971-up Fuse Block on your harness. This horn relay Chrysler part number 3579204 (1971-73 B and E Body) can be purchased separately under part NG1018.

NOTICE SHEET

92963521