****CAUTION****

READ ALL INSTRUCTIONS BEFORE INSTALLING THIS MODIFED FORWARD LAMP HARNESS

This forward lamp harness is modified for a SI series internally regulated alternator.

In this application a modified engine wiring harness is required to complete the charging system upgrade.

Caution should be used when installing this internally regulated alternator forward lamp harness to also install the correct matching modified engine harness for the appropriate vehicle make and model combination.

Do not attempt to use this harness with an unmodified or factory original engine harness as the charging system will not function correctly.

NOTE: The modified engine harness includes a black loose piece molded cap and is not needed with this forward lamp harness. See instruction sheet 92969202 included with the modified engine harness.

All remaining connections in this harness are the same as original forward lamp harness as outlined in the service and assembly manuals.

For any questions concerning installation of this harness please call our technical support line at (562)926-9552.



INSTRUCTION SHEET

FORWARD LAMP HARNESS WITH SI SERIES INTERNALLY REGULATED ALTERNATOR

PART N

92970283